

ANTI-LOCK BRAKE SYSTEM

Fig. 2: ABS Hydraulic Control Unit Line Routing & Bleeding Ports


Courtesy of Subaru of America, Inc.

1995 Subaru SVX

For Dog Nuts

Copyright © 1998 Mitchell Repair Information Company, LLC

Wednesday, June 02, 2004 06:46PM



93C02000